Dart .	Aeros	pace	Ltd

W/O:		WORK ORDER CHANGES							
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgf	Approval QC Inspector		
07/05/16	1	w/o split	ml	07/05/16	1	CAOSTU	20024		
A105-3"	G.	Applied contact cement	ZMF	074			-1-0		

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	_ Date:	
			QA: N/C Closed:	Date:	

NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCR)			
11 50 - 7 - 7 - 7 - 7 - 7 - 7		Description of NC		Corrective Action Section B		Verification	Annewal	Anneousl
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector

NOTE: Date & initial all entries

Monday, 5/14/2007 7:14:17 AM Date: User: Kim Johnston **Process Sheet** Drawing Name: HARNESS ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D412702105B Job Number: 32334 Job Number: Description: Seq. #: Machine Or Operation: AN960JD10LL Washer 6.0 4.0000 Each(s)/Unit Total: 20.0000 Each(s) Comment: Qty.: Washer M11763-MS21042L3 7.0 Comment: Qty.: 20.0000 Each(s) 4.0000 Each(s)/Unit Total: D35693 8.0 5.0000 Each(s) Comment: Qty.: 1.0000 Each(s)/Unit Total: DECAL batch: SMALL & MEDIUM FAB RESOURCE 1 9.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble as per dwg ICA D412-702 p.79 INSPECT WORK TO CURRENT STEP 10.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 PACKAGING RESOURCE #1 11.0 Comment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PPP D412-702-105B Location: PPP Rev: Job Completion


W/O:		WORK ORDER CHANGE	S				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
07/03/23	9	Marine adhesine Seatant glue M 104 524	SA	67/05/24	0		
Part No:		PAR #: Fault Category:	NCR: Yes	No DQ/	A: <u> </u>	Date: _<	07/05/24

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC Corrective Action Section B			Verification	A	A		
DATE ST	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	QC Inspecto	
A05:24	9.0	D3569-3 over not stick to the buckle, even with the recomended walkesize 3M fast cure 5200	Ms	Apply a light cost of contact coment to bench the instel to the bouckle.	83 भागाय		AB, 37/05/24	0705-20	
			OFFICIL	M102525		10705-24			


NOTE: Date & initial all entries

ICA-D412-702

ICA Page 79 (80 blank) of 98



DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B HARNESS ASSEMBLIES (BELTS, K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



NCONTROLLED COPY DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIES (BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN) WITHOUT NOTICE

SHOP COPY RETURN TO

ENGINEERING

. COPYRIGHT © 2004 BY DART AEROSPACE LTD. .

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

25-00-00

Page 49 (50 blank) of 68